BoardDocs® Pro Page 1 of 2



Agenda Item Details

Meeting Jun 14, 2021 - Regular Meeting

Category 8. Consent Agenda

Subject 8.21 Tag-On Bid Purchasing Over \$25,000: ITB 21-968-173 Bleacher Repair &

Motorization, presented by Vince Windham, Program Director, Purchasing, and

recommended by the Superintendent for approval.

Access Public

Type Action (Consent)

Fiscal Impact Yes

Budgeted Yes

Budget Source Capital Funds, Project 2310-District Wide Minor Repair & Maintenance

Recommended Action Motion to approve tagging on to ITB 21-968-173 Bleacher Repair & Motorization

through Pinellas County Schools, effective through May 10, 2022.

Public Content

Request approval to tag on to ITB 21-968-173 Bleacher Repair & Motorization through Pinellas County Schools. The bid is based on fixed prices and will be used on an as needed basis. Funding will be paid from Capital Funds, Project 2310-District Wide Minor Repair & Maintenance. The contract is effective through May 10, 2022. Copies of the award documents are attached.

For additional information, please contact Steve Bolton, Program Director, Maintenance, at (850) 689-7159.

AWARD DOCUMENTS FOR ITB 21-968-173.pdf (473 KB)

Administrative Content

Our adopted rules of Parliamentary Procedure, Robert's Rules, provide for a consent agenda listing several items for approval of the Board by a single motion. Documentation concerning these items have been provided to all Board members and the public in advance to assure an extensive and thorough review. Items may be removed from the consent agenda at the request of any board member.

Motion & Voting

Motion to approve the Consent Agenda and all of the Consent Agenda items as recommended by the Superintendent

Motion by Diane Kelley, second by Marti Gardner.

BoardDocs® Pro Page 2 of 2

Final Resolution: Motion Carries

Yes: Tim Bryant, Linda Evanchyk, Marti Gardner, Diane Kelley, Lamar White



PURCHASING AGENDA ITEM

School Board of Pinellas County, Florida

School Board Meeting of: May 11, 2021

	1001 20414 1110011	118 01. 1.14.5			
Bid No: 21-96	68-173	Bid Title: Bl	eacher I	Repair &	Motorization
Original Bid No:	N/A				
Recommend approv	al of this agenda item und	der the specific cate	gory chec	ked below	
Agenda Item Categ	ories:				
☐ Revised Award * ☐ Renewal of Contract		Re-Award (partial/who on *	ole) * 🔲 (tension * To	State Contracterm:	ct per 6A-1.012 (5)
Contract Period:	05/11/21 thru 05/1	0/22] N/A - 0	One Time	Purchase
Contract Value:	\$ 100,000.00				
Contract Type:	Estimated Dollar Amount	Firm, Fixed Dollar Amount	_	Fixed Prices	Firm, Fixed Fees or Discounts
Renewal Options:	No. of Terms Remaining	Length of Each Term	E	ength of ach Term	None
* Rationale/Reason	•	6-months	-	· year	
Reason for Sub	mittal to Board Under S	eparate Cover:			
Bidders Solicited: 235	Bids Received: <u>1</u> La	te Bids: 0 Rejected	Bids: <u>0</u>	N/A - Bio	ds Not Required
Submitted By:	Linda M. Balcombe,		For:	County V	Vide
Title:	Director, Purchasing	g Department			
Requested By:	Michael He		Buyer:	Christine	Roney
ı iile:	Director, ivianifeliane	o Department			

Recommended award by vendor as follows: (see attached)

CHARRON SPORTS SERVICES, INC.

Provide all equipment, labor and materials necessary to repair, motorize and refurbish various types of gymnasium bleachers and basketball backstops on an as needed basis, county wide, per specifications.

	A	В	С	D	E
	A	D D		THE	
		INTERKAL/		FOLDING	KODIAK
	MEDART/	V.O.S./		BLEACHER	INDUSTRIE
DESCRIPTION	SAFWAY	HUSSEY	BERLIN	COMPANY	SLTD.
Perform in-place	2,000	TIODOL I	DURLIN		
wood cleaning					
and refinishing on					
one (1) typical					
sixteen (16) ft.					
section x ten (10)					
rows high of					
telescopic					
bleachers †	\$204.60	\$306.90	\$20.46	\$306.90	\$598.50
Replace missing	\$204.00	\$300.70	\$20.40	\$300.70	Ψ370.30
or broken wheels					
and axles	\$29.01	\$29.01	\$29.01	\$29.01	\$29.01
	\$29.01	\$29.01	\$29.01	\$29.01	\$29.01
Replace missing					
or non-					
functioning base	Ø10 /1	-/-	7/2	n/a	1.00
springs	\$18.41	n/a	n/a	II/a	1.00
Replace first row					
locking assemblies	007.00	607.00	007.00	¢07.00	\$87.98
	\$87.98	\$87.98	\$87.98	\$87.98	\$67.96
Replace missing					
or worn brake	610.41	610.41	610 41	610.41	¢10.41
pads	\$18.41	\$18.41	\$18.41	\$18.41	\$18.41
Replace and/or					
rebuild first row					
lock release					İ
linkage and first					
row brake	6101.20	6101.20	671.61	6101.20	6101.20
assembly	\$101.28	\$101.28	\$71.61	\$101.28	\$101.28
Replace and/or					
rebuild damaged	0.05	025.57	0.05	005.57	620.46
row locks/stops	\$.05	\$25.57	\$.05	\$25.57	\$20.46
Straighten bent	0.15.00	0115.00	#115.00	#115.00	0115.00
uprights	\$115.00	\$115.00	\$115.00	\$115.00	\$115.00
Repair/rebuild	005.55	006.05	000.00	0100.25	007.10
uprights	\$25.57	\$86.95	\$30.69	\$100.25	\$97.18
Repair/reinforce					
damaged uprights		000.57	000.50	000.67	000.05
and bracing	62.41	\$92.07	\$30.69	\$92.07	\$92.07
Adjust cantilevers	\$14.32	\$15.34	\$1.00	\$15.34	\$15.34
Replace					
cantilevers	\$133.01	\$133.01	\$133.01	\$133.01	\$133.01
Weld stress					
fractures	\$\$71.61	\$71.61	\$60.00	\$71.61	\$71.61
Repair/rebuild	\$.90	\$5.00	\$1.00	\$5.00	\$10.23

cantilever guides					
Repair/rebuild					
cantilever stops	\$2.00	\$10.23	\$10.23	\$10.23	\$15.34

	A	В	C	D	E
			表面复杂症	THE	A STATE OF STATE
	100	INTERKAL	[A. A. 5 29]	FOLDING	KODIAK
	MEDART/	V.O.S.	(支撑) 整体(BLEACHER	INDUSTRIES
DESCRIPTION	SAFWAY	HUSSEY	BERLIN	COMPANY	LTD.
Replace each					
damaged/broken					
plastic seat					
module	\$n/a	\$115.00	\$n/a	\$115.00	\$115.00
Weld seat baffles	\$35.80	\$35.80	\$35.80	\$35.80	\$35.80
Weld seat bracket	\$35.80	\$35.80	\$35.80	\$35.80	\$35.80
Repair cracked					
boards	\$10.23	\$10.23	\$30.69	\$30.69	\$30.69
Replace spring	\$26.60	n/a	n/a	n/a	\$26.60
Replace clip	\$26.60	n/a	n/a	n/a	n/a
Replace lower					
guide (base)	\$81.84	\$40.92	n/a	\$51.15	\$51.15
Replace nylon					
guide	\$10.23	n/a	n/a	\$5.00	\$25.57
Replace nylon					
rollers	\$12.28	n/a	n/a	\$28.28	\$25.57
Replace lower					
stop	\$12.28	n/a	n/a	\$2.00	\$.69
Replace scissors	,	,		,	,
linkage	n/a	n/a	\$25.57	n/a	n/a
Replace channel	n/a	n/a	\$15.34	n/a	n/a
Replace	,	,	.	,	,
bushing/pin	n/a	n/a	\$1.00	n/a	n/a
Supply and install					
self-storing rails	£170.00	£170.00	6170.02	#170 02	6170.02
(aluminum)*	\$179.02	\$179.02	\$179.02	\$179.02	\$179.02
Supply and install self-storing rails					
(powder-coated					
steel)*	\$92.07	\$140.15	\$75.00	\$140.15	\$140.15
Supply and install	Ψ92.07	φ170.13	\$13.00	φ140.13	ψ140.13
self-storing mid-					
aisle handrails	\$230.17	\$230.17	\$230.17	\$230.17	\$207.66
alore mandrants	Ψ230.17	Ψ230.17	Ψ230.17	Ψ230.17	Ψ207.00
Replace motor					
drive wheels	\$511.50	\$275.75	\$511.50	\$579.00	\$511.50
	77777	72.0.70	3311.30	3077.00	2011.00
Supply and install					
motor operation					
system with				1	
controls (sections					
tied together as					
banks)**	\$1534.50	\$1649.00	\$204.60	\$1534.50	\$1841.40
Replace drive					
motor	\$575.50	\$928.70	\$575.50	\$799.00	\$845.00

Replace					
transmission	n/a	\$920.70	n/a	n/a	n/a

	Α	В	С	D	Е
				THE	211
		INTERKAL/		FOLDING	KODIAK
	MEDART/	V.O.S./		BLEACHER	INDUSTRIES
DESCRIPTION	SAFWAY	HUSSEY	BERLIN	COMPANY	LTD,
Cut off 9" to 10"					
of sections where					
wall interferes					
with rails.	\$971.85	\$971.85	\$971.85	\$971.85	\$971.85
Replace upper					
tier stops and					
cantilever guides	\$5.00	\$12.28	\$5.00	\$12.28	\$12.28
Furnish & install					
floor anchors	\$10.23	\$10.23	\$10.23	\$10.23	\$10.23
Furnish & install					
wall toggle bolts	\$25.57	\$25.57	\$25.57	\$25.57	\$25.57
Furnish & install					
wall anchor					
brackets	\$19.44	\$19.44	\$19.44	\$19.44	\$19.44
Furnish & install					
outrigger wheels	\$31.71	\$31.71	\$31.71	\$31.71	\$31.71
Furnish & install					
1/4" angle					
cantilever assist					
bracket					
reinforcement	n/a	\$35.80	n/a	n/a	n/a
Furnish & install					
skirt board hinge	\$28.64	\$28.64	\$28.64	\$28.64	\$28.64
Supply & install					
replacement					
boards, fir	\$ 10.84 /l.f.	\$ 10.84 /l.f.	\$ 10.84/l.f.	\$ 10.84 /l.f.	\$ 10.84 /l.f.
Supply & install					
replacement					
boards, pine	\$10.84 /l.f.	\$ 10.84 /l.f.	\$ 5.63 /l.f.	\$ 10.84 /l.f.	\$ 10.84 /l.f.
Supply & install					
replacement					
boards, plywood					
deck (2' x 8'					
piece)	\$81.84	\$81.84	\$81.84	\$81.84	\$81.84
Install 4" filler	6716/16	6716/16	6716/16	6716/16	¢ 7 16 /1 £
board to fill up gap	\$ 7.16 /l.f.	\$ 7.16 /l.f.	\$ 7.16 /l.f.	\$ 7.16 /l.f.	\$ 7.16 /l.f.
Furnish & install					
bleacher motion					
alert signal Edwards Adapta					
Beacon Signal					
Model 51R-N5-					
40W or approved					
equal	\$491.11	\$491.11	\$491.11	\$491.11	\$491.11
- cquai	φ+21.11	φ471.11	φ471.11	φ=71.11	Ψ7/1.11

		-			
	_	_	_	_	
	A	В	C	D	E
		基本基础基础		THE	用品品基础
	沙珠型基本的	INTERKAL/	15 0 c 51	FOLDING	KODIAK
	MEDARTA:	V.O.S./		BLEACHER	INDUSTRIES
DESCRIPTION *	SAFWAY	HUSSEY	BERLIN	COMPANY	PETD:
Retrofit existing					
bleachers to					
provide a 16'-0"					
section of 48"					
deep handicapped					
seating at floor					
level. Price to					
include sides &					
back rails (fixed					
section)	\$1227.60	\$1227.60	\$1227.60	\$1227.60	\$1227.60
Retrofit existing					
bleachers to					
provide a 16'-0"					
section of 48"					
deep handicapped					
seating at floor					
level. Price to					
include sides &					
back rails (one					
retractable					
section).	\$1227.60	\$1227.60	\$1227.60	\$1227.60	\$1227.60
Retrofit existing					
bleachers to					
provide a 16'-0"					
section of 48"					
deep handicapped					
seating at floor					
level. Price to					
include sides &					
back rails (two					
parts, retractable					
section).	\$2148.30	\$2148.30	\$2148.30	\$2148.30	\$2148.30
Furnish & install	Ψ2170.JU	ΨΔ170.30	ψ2170.30	φ4170.30	ψ4170.30
seat level aisles					
from 36" x 42" in					
width, covering					
the distance	!				
between the seat					
board & the front					
riser of the row					
above.	\$92.07	\$97.18	\$15.34	\$70.80	\$70.80
Furnish & install	Φ74.U/	φ 7 /.1δ	φ13.34	\$79.80	\$79.80
deck level aisles.	\$92.07	\$71.61	\$71.61	\$70.90	\$70.80
Add twist			\$71.61	\$79.80	\$79.80
Add twist	\$14.32	\$14.32	\$14.32	\$14.32	\$14.32

brackets to					
support end rails					
h.T					
	A	В	C	D	E
	23.数据用AAA	5. 2700 Carlotte	V 725 1	THE	3.1
		INTERKAL/	解析法 医后肢	FOLDING	KODIAK
The state of	MEDART	V.O.S./	BERLIN	BLEACHER	INDUSTRIE S LTD.
DESCRIPTION Add delta	SAFWAY	HUSSEY	BERLIN	COMPANY	2 PID:
brackets to	01400	61400	614.00	614.00	61400
support end rails	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00
Replace front row	040.00	040.00	040.00	040.00	040.02
step hinges	\$40.92	\$40.92	\$40.92	\$40.92	\$40.92
Add weights to					
motor units for	0.44.00	0.4.6.00	046.00	046.02	046.02
even traction	\$46.03	\$46.03	\$46.03	\$46.03	\$46.03
On-site delivery					
of bleachers					
(from one school					
to another school)					
price per section	\$2148.30	\$2148.30	\$2148.30	\$2148.30	\$2148.30
Moving and re-					
anchoring of					
bleachers within					
the gymnasium -					
price per section	\$900.24	\$900.24	\$900.24	\$900.24	\$900.24
Moving and re-					
anchoring of					
bleachers within					
the school – price	*****				
per section	\$1227.60	\$1227.60	\$1227.60	\$1227.60	\$1227.60
Labor cost per					
hour for repairs					
not indicated					
above or for					
electrical trouble	*****				
shooting	\$97.18	\$97.18	\$97.18	\$97.18	\$97.18

Spot sand rough edges, clean spot stain, remove graffiti & apply two (2) coats of water borne polyurethane to bleacher boards.
 Supply specifications and drawings per bid package.
 Supply specifications and drawings per bid package. Price is per motor unit and is to be all inclusive.

BASKETBALL BACKSTOPS

DESCRIPTION	COST
Service one (1) basketball backstop as detailed in Division 13, Section 13125B	
Part 2, Item 2.4 A pages 42 and 43 of specifications	\$119.50
Weld stress crack	\$86.95
Replace pulley	\$100.25
Replace cable (per backstop)	\$173.91
Straighten bent structural steel member (to be approved by Project	
Leader/Structural Engineer)	\$859.32
Replace wall pad	\$79.00
Replace steel pipe (per foot)	\$33.75
Replace pipe fitting	\$76.72
Replace limit switch assembly	\$562.65
Replace key switch	\$189.25
Repair/rebuild existing limit switch	\$521.73
Repair/rebuild existing electric winch	\$1227.60
Replace manual winch (Lyn Russ M/1000)	\$971.85
Replace manual winch (Tork)	\$971.85
Install Lyn Russ A-1000 or DPI WN/-5007 electric winch 115 volt key switch	
operation (power supplied by owner), price to include all conduits	\$1495.00
Install Tork electric winch (power supplied by owner), price to include all	
conduits	\$1499.00
Install cable tension cord with clamps	\$56.26
Install Lyn Russ Auto-Lok safety strap or approved equal (1500# free fall load)	\$470.58
Install Tork safety strap	\$479.00
Install remote receiver on winch	\$416.00
Furnish remote control to receiver	\$214.83
Rewire Key switches	\$97.18
Replace a set of backboard pads	\$271.09
Replace a break-away rim	\$317.13
Labor cost per hour for repairs not indicated above or for electrical trouble	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
shooting	\$76.72



100% Student Success

Missinn.

"Educate and prepare each student for college, career and life."

May 11, 2021

Charron Sport Services, Inc. 7733 Liberty Highway Liberty, South Carolina, 29657

Ref: Notice of Bid Award

Bid No. Bid#21-968-173,

Bid Name: Bleacher Repair & Motorization

Dear Sir:

On Tuesday, May 11, 2021, the School Board of Pinellas County, Florida awarded your company all or a portion of the above referenced bid. This is your official notification of contract award. A copy of the agenda item approved by our School Board is attached confirming the award to your company. Orders will be placed as needed for the duration of the one year contract period to authorize performance under the contract.

All purchases must be properly authorized in advance. Vendors must first obtain either a printed purchase order, a purchase order number or a purchasing card account number before commencing performance under a contract. Vendors shall take no directions to modify (increase, change, decrease, cancel) a purchase order, once issued, from anyone other than the buyer listed on the purchase order. Additional work must be authorized in advance by the buyer who will issue either a change order to the original purchase order or a supplemental purchase order. The vendor assumes all liability for any costs or damages incurred and payment will be denied for additional work if this procedure is not strictly followed.

To ensure timely payment, all original invoices should be submitted to the Accounts Payable Department, Pinellas County School Board, PO Box 2942, Largo, FL., 33779-2942. A minimum of thirty (30) days is required for payment. Photocopies of original invoices may be sent to other district personnel if they request it, but the original copies must be sent to the Accounts Payable Department. Only the Accounts Payable Department may direct you otherwise. Failure to follow this procedure may result in payment delays, Occasionally a school may issue its own internal purchase order. Invoices associated with a SCHOOL purchase order should be submitted directly to the school for payment. Do not send invoices associated with school purchase orders to the Accounts Payable Department.

For your information, the administrator of this contract is Hector Camacho. Hector can be reached at (727) 547-7116 if you have questions or need assistance.

Thank you for your bid and your interest in Pinellas County Schools.

Sincerely,

Christine Roney Buyer II

attachments

ADMINISTRATION BUILDING 301 Fourth St. SW P.O. Box 2942 Largo, FL 33779-2942 Ph. (727) 588-6000

SCHOOL BOARD OF

Chairperson

Carol J. Cook

Lisa N. Cane

Bill Dudley Caprice Edmond Laura Hine

Vice Chairperson Eileen M. Long

Nicole M. Carr, Ph.D.

Superintendent

Michael A. Grego, Ed.D.

PINELLAS COURTY, FLORIDA

0