

Agenda Item Details

Apr 24, 2017 - Regular Meeting Meeting

7. Consent Agenda Category

7.10 ITB 17-03 Fire Extinguishers and Kitchen Hood Systems Inspection, Maintenance Subject

and Repair, presented by Vince Windham, Program Director, Purchasing, and

recommended by the Superintendent for approval.

Public Access

Action (Consent) Type

Fiscal Impact Yes

Yes

Budgeted

Budget Source Capital Funds, Project 2395 Safety/ADA - Districtwide

Recommended Motion to approve the Committee's recommendation to award ITB 17-03 Fire

Extinguishers and Kitchen Hood Systems Inspection, Maintenance and Repair to The Action

Hiller Companies.

Public Content

Request approval of the Committee's recommendation to award ITB 17-03 Fire Extinguishers and Kitchen Hood Systems Inspection, Maintenance and Repair to The Hiller Companies, based on fixed prices. Funding will be paid from Capital Funds, Project 2395 Safety/ADA - District wide. The contact is effective May 10, 2017 through May 9, 2020 and a copy of the award tabulation is attached.

For additional information, please contact Steve Bolton, Director, Facilities Planning and Maintenance Support Services at (850) 689-7159.

ITB 17-03_TAB.pdf (29 KB)

Administrative Content

Our adopted rules of Parliamentary Procedure, Robert's Rules, provide for a consent agenda listing several items for approval of the Board by a single motion. Documentation concerning these items have been provided to all Board members and the public in advance to assure an extensive and thorough review. Items may be removed from the consent agenda at the request of any board member.

Motion & Voting

Motion to approve the Consent Agenda as amended and all of the Consent Agenda items as recommended OOLBO by the Superintendent

OHALOOSA C

4/25/2017

Motion by Rodney Walker, second by Dewey Destin.

Final Resolution: Motion Carries

Yes: Tim Bryant, Dewey Destin, Melissa Thrush, Rodney Walker, Lamar White

https://www.boarddocs.com/fl/okaloosa/Board.nsf/Private?open&login

REPAIR PARTS: PORTABLE EXTINGUISHERS		VENDOR The Hiller Companies			
SIGNED BID	DESCRIPTION	UNIT PRICE			
Yes	1. HOSES	\$1.00			
	2. O-RINGS	\$1.75			
	3. GAUGES	\$2.72			
	4. TRIGGER ASSEMBLY	\$3.00			
	5. INSTALL NEW WALL BRACKET	\$0.00			
	6. INSTALL NEW VALVE STEM	\$3.60			
1. TYPE	INSPECTION PRICE EACH	RECHARGE PRICE EACH	HYDROSTATIC TEST PRICE EACH	SIX YEAR MAINT.	REPLACEMENT COST FOR NEW EXTINGUISHER
CO ₂ - 5LB.	\$0.25	\$2.00	\$6.00	NOT REQUIRED	\$120.00
CO ₂ – 10LB.	\$0.25	\$3.00	\$6.00	NOT REQUIRED	\$162.00
CO ₂ - 15LB.	\$0.25	\$7.00	\$6.00	NOT REQUIRED	\$163.00
PRESSURIZE D WATER	\$1.00	\$1.00	\$6.00	NOT REQUIRED	\$75.00
K-GRADE	\$1.00	\$90.00	\$10.00	NOT REQUIRED	\$195.00
2. TYPE: DRY CHEMICAL	INSPECTION PRICE EACH	RECHARGE PRICE EACH	HYDROSTATIC TEST PRICE EACH	SIX YEAR MAINT.	REPLACEMENT COST FOR NEW EXTINGUISHER
2 3/4 LB. BC	\$0.50	\$0.50	\$0.50	\$0.50	\$24.53
2 3/4 LB. ABC	\$0.50	\$2.00	\$2.00	\$2.00	\$27.00
5 LB. BC	\$1.50	\$4.00	\$4.00	\$4.00	\$37.00
5-6 LB. ABC	\$3.25	\$14.00	\$10.00	\$16.00	\$42.00
6-7 LB. BC	\$1.50	\$4.00	\$4.00	\$4.00	\$49.39
10 LB. BC	\$1.50	\$10.00	\$8.00	\$10.00	\$59.00
10 LB. ABC	\$3.25	\$17.00	\$10.00	\$20.00	\$63.00
11 LB HALOTRON	\$1.50	\$182.71	\$2.00	\$45.00	\$302.00
20 LB. BC	\$1.50	\$15.00	\$8.00	\$15.00	\$94.86
20 LB. ABC	\$3.25	\$20.00	\$8.00	\$22.00	\$123.00

AUTOMATIC KITCHEN HOOD EXTINGUISHING SYSTEMS UNIT COST FOR SEMI-ANNUAL INSPECTION AND FUSIBLE LINK REPLACEMENT

UNIT PRICE	33 SYSTEMS
\$59.00	\$1,947.00

REPAIR PARTS: PORTABLE EXTINGUISHERS		VENDOR B & C Fire Safety, Inc.			
SIGNED BID	DESCRIPTION	UNIT PRICE			
Yes	1. HOSES	\$9.00			
	2. O-RINGS	\$1.00			
	3. GAUGES	\$5.50			
	4. TRIGGER ASSEMBLY	\$5.00			
	5. INSTALL NEW WALL BRACKET	\$4.50			
8 · · · ·	6. INSTALL NEW VALVE STEM	\$3.50			
1. TYPE	INSPECTION PRICE EACH	RECHARGE PRICE EACH	HYDROSTATIC TEST PRICE EACH	SIX YEAR MAINT.	REPLACEMENT COST FOR NEW EXTINGUISHER
CO ₂ - 5LB.	\$2.00	\$4.00	\$10.00	NOT REQUIRED	\$160.00
CO ₂ – 10LB.	\$2.00	\$8.00	\$10.00	NOT REQUIRED	\$208.00
CO ₂ - 15LB.	\$2.00	\$12.00	\$10.00	NOT REQUIRED	\$251.00
PRESSURIZE D WATER	\$2.00	\$5.00	\$10.00	NOT REQUIRED	\$102.00
K-GRADE	\$3.00	\$95.00	\$15.00	\$95.00	\$162.00
2. TYPE: DRY CHEMICAL	INSPECTION PRICE EACH	RECHARGE PRICE EACH	HYDROSTATIC TEST PRICE EACH	SIX YEAR MAINT.	REPLACEMENT COST FOR NEW EXTINGUISHER
2 3/4 LB. BC	\$2.00	\$7.00	\$8.00	\$7.00	\$32.80
2 3/4 LB. ABC	\$2.00	\$7.00	\$8.00	\$7.00	\$32.50
5 LB. BC	\$2.00	\$10.00	\$8.00	\$10.00	\$44.50
5-6 LB. ABC	\$2.00	\$10.00	\$8.00	\$10.00	\$44.50
6-7 LB. BC	\$2.00	\$10.00	\$8.00	\$10.00	\$45.50
10 LB. BC	\$2.50	\$15.00	\$8.00	\$15.00	\$74.00
10 LB. ABC	\$2.50	\$15.00	\$8.00	\$15.00	\$74.50
11 LB HALOTRON	\$2.50	\$150.00	\$12.00	\$150.00	\$350.00
20 LB. BC	\$2.50	\$20.00	\$8.00	\$20.00	\$125.00
20 LB. ABC	\$2.50	\$20.00	\$8.00	\$20.00	\$130.00

AUTOMATIC KITCHEN HOOD EXTINGUISHING SYSTEMS UNIT COST FOR SEMI-ANNUAL INSPECTION AND FUSIBLE LINK REPLACEMENT

UNIT PRICE	33 SYSTEMS
\$78.00	\$2,574.00

TABULATION AND RECOMMENDATION ITB 17-03 FIRE EXTINGUISHERS AND KITCHEN HOOD SYSTEMS INSPECTION/MAINTENANCE/REPAIR - OPENING 4/4/17 @ 2:00PM CT

OFFERS FROM THE VENDORS LISTED HEREIN ARE THE ONLY OFFERS RECEIVED TIMELY AS OF THE ABOVE OPENING DATE AND TIME. ALL OTHER OFFERS SUBMITTED IN RESPONSE TO THIS SOLICITATION, IF ANY ARE HEREBY REJECTED AS LATE

VENDORS WHICH RESPONDED NO BID: NONE VENDORS WHICH WERE NON-RESPONSIVE: NONE

RECOMMENDATION FOR ITB 17-03 FIRE EXTINGUISHERS AND KITCHEN HOOD EXTINGUISHING SYSTEMS INSPECTION/MAINTENANCE/REPAIR

TERM OF CONTRACT: THREE (3) YEAR PERIOD BEGINNING MAY 10, 2017 THRU MAY 9, 2020

COMMITTEE: Steve Bolton, Director - Facilities & Maintenance

John Jamieson, Safety Foreman

COMMITTEE RECOMMENDS AWARD TO THE LOWEST RESPONSIVE & RESPONSIBLE BIDDER THAT COMPLIES WITH ALL PROVISIONS OF THIS SOLICITATION FOR FIXED PRICES TO: The Hiller Companies.

FUNDING: 3427 7400 0684 9025 2395

"FAILURE TO FILE A PROTEST WITHIN THE TIME PRESCRIBED IN FLORIDA STATUTES 120.57(3) SHALL CONSTITUTE A WAIVER OF PROCEEDING UNDER CHAPTER 120, FLORIDA STATUTES"

POSTED: 4/6/17 9:30 AM CT