

Agenda Item Detai	Agenda Item Details							
Meeting	Apr 23, 2018 - Regular Meeting							
Category	8. Consent Agenda							
Subject	8.17 Tag-On Bid RFQu 18-968-525 Bleacher Repair & Motorization, presented by Vince Windham, Program Director, Purchasing, and recommended by the Superintendent for approval.							
Access	Public							
Туре	Action (Consent)							
Fiscal Impact	Yes							
Budgeted	Yes							
Budget Source	Capital Funds, Project 2310 District Wide - Minor Repair & Maintenance							
Recommended Actio	n Motion to approve tagging on to RFQu 18-968-525-MR Bleacher Repair & Motorization through Pinellas County Schools.							

Public Content

Request approval to tag on to RFQu 18-968-525-MR Bleacher Repair & Motorization through Pinellas County Schools. The bid offers fixed prices and will be used on an as needed basis to repair, motorize and refurbish various types of gymnasium bleachers and basketball backstops. Funding will be paid from Capital Funds, Project 2310 District Wide - Minor Repair & Maintenance. The contract is effective March 25, 2018 through March 24, 2019. A copy of the award tabulation is attached.

For additional information, please contact Steve Bolton, Director, Facilities Planning and Maintenance Support Services at (850) 689-7159.

TAG-ON BID RFQu 18-968-525 BLEACHER REPAIR & MOTORIZATION.pdf (197 KB)

Administrative Content

Our adopted rules of Parliamentary Procedure, Robert's Rules, provide for a consent agenda listing several items for approval of the Board by a single motion. Documentation concerning these items have been provided to all Board members and the public in advance to assure an extensive and thorough review. Items may be removed from the consent agenda at the request of any board member.

Motion & Voting

Motion to approve the Consent Agenda and all of the Consent Agenda items as recommended by the Superintendent

Motion by Rodney Walker, second by Dewey Destin. Final Resolution: Motion Carries Yes: Tim Bryant, Dewey Destin, Melissa Thrush, Rodney Walker, Lamar White





Vision 100% Student Success

Mission "Educate and prepare each student for college, career and life "

March 25, 2018

Charron Sports Services, Inc. 7733 Liberty Hwy. Liberty, SC 29657 ADMINISTRATION BUILDING 301 Fourth St SW PO Box 2942 Largo, FL 33779 2942 Ph (727) 588 6000

SCKOOL BOARD OF PINELIAS COUNTY, FLORIDA Chairperson Rene Flowers

> Vice Chairperson Peggy L O' Shea

> > Carol J Cook Terry Krassner Joanne Lentino Linda S Lerner Eileen M Long

Superintendent Michael A. Greyo, Ed D

Ref: Notice of Award RFQu No. <u>18-968-525</u>, RFQu Name: <u>Bleacher Repair & Motorization</u>

Dear Sir:

Your company has been recommended for award on the above referenced Request for Quotation. Orders will be placed as needed for the duration of the year contract period.

All purchases must be properly authorized in advance. Vendors must first obtain a printed purchase order, a purchase order number or a purchasing card account number before commencing performance under a contract. Vendors shall take no directions to modify (increase, change, decrease, cancel) a purchase order, once issued, from anyone other than the buyer listed on the purchase order. Additional work must be authorized in advance by the buyer who will issue either a change order to the original purchase order or a supplemental purchase order. The vendor assumes all liability for any costs or damages incurred and payment will be denied for additional work if this procedure is not strictly followed.

To ensure timely payment, all original invoices should be submitted to the Accounts Payable Department, Pinellas County School Board, PO Box 2942, Largo, FL., 33779-2942. A minimum of thirty (30) days is required for payment. Photocopies of original invoices may be sent to other district personnel if they request it, but the original copies must be sent to the Accounts Payable Department. Only the Accounts Payable Department may direct you otherwise. Failure to follow this procedure may result in payment delays. Occasionally a school may issue its own internal purchase order. Invoices associated with a SCHOOL purchase order should be submitted directly to the school for payment. Do not send invoices associated with school purchase orders to the Accounts Payable Department.

For your information, the administrator of this contract is Hector Camacho. Hector can be reached at (727) 547-7119 if you have questions or need assistance.

Thank you for your response and your interest in Pinellas County Schools.

Sincerely, Christine Roney

Buyer II

attachments

0

REQUEST FOR QUOTATION (RFQu) Information Page

Title:	Bleacher H	Repair &	Motoriz	ation RI	Qu #:		18-968-525
Original E	Bid or RFC)u #:	N/A				
Contract Period:	03/25/	<u>18</u> to	<u>03/24/1</u>	9 Contract Value:	\$ <u>38,0</u>	<u>00.00</u>	N/A Single Purchase
Contract Ty		imated Iar Amount		n, Fixed llar Amount	⊠ Firm, F Unit Pi		Firm, Fixed Fees or Discounts
Renewal Op	otions:	No. of T Remain 2		Length of Each Term 6-months	Eac	ngth of ch Term year	None
Requested	•		chael Hewe		Buyer:	Christin	ne Roney
	Title: D	,	intenance	Department e			

Award by vendor as follows:

CHARRON SPORTS SERVICES, INC.

Provide all equipment, labor and materials necessary to repair, motorize and refurbish various types of gymnasium bleachers and basketball backstops on an as needed basis, county wide, per specifications.

	Α	B	С	D	E	F
DESCRIPTION	MEDART/ SAFWAY	INTERKAL/ V.O.S./ HUSSEY	WAYNE	BERLIN	THE FOLDING BLEACHE R COMPANY	KODIAK INDÜSTRIE S LTD.
Perform in-place wood cleaning						
and refinishing						
on one (1)						
typical sixteen (16) ft. section x						
ten (10) rows						
high of	\$200.00	\$300.00	\$20.00	\$20.00	\$300.00	\$635.00

<u> </u>	r	1			T	
telescopic						
bleachers †						
Replace missing						
or broken wheels	6 20.07	(100 a)	000.00	***	600.2 (1 00 26
and axles	\$28.36	\$28.36	\$28.36	\$28.36	\$28.36	\$28.36
Replace missing						
or non-						
functioning base						
springs	\$18.00	n/a	1.00	n/a	n/a	1.00
Replace first row						
locking						
assemblies	\$86.00	\$86.00	\$86.00	\$86.00	\$86.00	\$86.00
Replace missing						
or worn brake						
pads	\$18.00	\$18.00	\$18.00	\$18.00	\$18.00	\$25.00
Replace and/or						
rebuild first row						
lock release						
linkage and first					1	
row brake						
assembly	\$99.00	\$99.00	\$96.00	\$70.00	\$99.00	\$99.00
Replace and/or						
rebuild damaged						
row locks/stops	\$.05	\$25.00	\$.05	\$.05	\$25.00	\$20.00
Straighten bent						
uprights	\$115.00	\$115.00	\$115.00	\$115.00	\$115.00	\$115.00
Repair/rebuild						
uprights	\$20.00	\$85.00	\$10.00	\$98.00	\$98.00	\$95.00
Repair/reinforce				\$70.00	\$20.00	
damaged						
uprights and						
bracing	60.00	\$90.00	\$25.00	\$30.00	\$105.00	\$105.00
Adjust		ψ20.00	ψ23.00	\$30.00	1 4103.00	φ105.00
cantilevers	\$14.00	\$15.00	\$.90	\$1.00	\$15.00	\$15.00
Replace	φ1 4 .00	\$13.00	. .90	\$1.00	\$15.00	\$13.00
cantilevers	\$131.00	\$121.00	\$121.00	\$121.00	\$121.00	\$121.00
Weld stress	\$121.00	\$131.00	\$131.00	\$131.00	\$131.00	\$131.00
	\$\$70.00	\$70.00	670.00	\$70.00	\$70.00	670.00
fractures	\$\$70.00	\$70.00	\$70.00	\$70.00	\$70.00	\$70.00
Repair/rebuild	.		0.00		0.5.00	610.00
cantilever guides	\$.90	\$5.00	\$.90	\$1.00	\$5.00	\$10.00
Repair/rebuild	60 5 5					
cantilever stops	\$2.00	\$10.00	\$1.00	\$10.00	\$10.00	\$15.00

	Α	В	С	D	E	F
DESCRIPTION	MEDART/ SAFWAY	INTERKAL/. V.O.S. /HUSSEY	WAYNE	BERLIN	THE FOLDING BLEACHE R COMPANY	KODIAK INDUSTRIES LTD.
Replace each damaged/broken plastic seat module	\$n/a	\$120.00	\$1.00	\$1.00	\$120.00	\$120.00

Weld seat	T					
baffles	\$35.00	\$35.00	\$35.00	\$35.00	\$35.00	\$35.00
Weld seat	\$55.00	\$35.00			\$55.00	
bracket	\$35.00	\$35.00	\$35.00	\$35.00	\$35.00	\$35.00
Repair cracked						
boards	\$10.00	\$10.00	\$30.00	\$30.00	\$30.00	\$30.00
Replace spring	\$26.00	n/a	\$26.00	n/a	n/a	\$26.00
Replace clip	\$26.00	n/a	n/a	n/a	n/a	n/a
Replace lower						
guide (base)	\$80.00	\$40.00	\$80.00	n/a	\$50.00	\$50.00
Replace nylon						
guide	\$10.00	n/a	n/a	n/a	\$5.00	\$25.00
Replace nylon						
rollers	\$12.00	n/a	n/a	n/a	\$12.00	\$25.00
Replace lower						
stop	\$12.00	n/a	n/a	n/a	\$2.00	\$30.00
Replace scissors						
linkage	n/a	n/a	n/a	\$25.00	n/a	n/a
Replace channel	n/a	n/a	n/a	\$15.00	n/a	n/a
Replace						
bushing/pin	n/a	n/a	n/a	\$1.00	n/a	n/a
Supply and install self-						
storing rails						
(aluminum)*	\$175.00	\$175.00	\$175.00	\$175.00	\$175.00	\$175.00
Supply and						
install self-					1	
storing rails						
(powder-coated	000.00	A 155.00				
steel)*	\$90.00	\$155.00	\$30.00	\$30.00	\$137.00	\$137.00
Supply and install self-						
storing mid-aisle handrails	\$225.00	\$225.00	\$225.00	\$225.00	\$225.00	\$203.00
114114115	\$223.00	\$223.00	\$223.00	\$223.00	\$223.00	\$203.00
Replace motor						
drive wheels	\$500.00	\$250.00	\$500.00	\$500.00	\$500.00	\$280.00
SITTO THEORY	\$300.00	φ230.00	\$500.00	\$500.00	\$500.00	\$200.00
Supply and						
install motor						
operation system						
with controls						
(sections tied						
together as						
banks)**	\$1500.00	\$1800.00	\$200.00	\$200.00	\$1500.00	\$1900.00
Replace drive			+20000	+======		41700.00
motor	\$400.00	\$900.00	\$450.00	\$450.00	\$700.00	\$700.00
Replace					+	
transmission	n/a	\$900.00	n/a	n/a	n/a	n/a

	A	В	C	D	E	F
DESCRIPTION	MEDART/	INTERKAL/	WAYNE	BERLIN	THE FOLDING	

	SAFWAY	V.O.S./ HUSSEY			BLEACHE	KODIAK INDUSTRIES LTD.
					COMPANY	al more than the
Cut off 9" to 10"						
of sections where						
wall interferes	*•••••••••••••	0050.00	0050.00	0050.00	\$050.00	\$050.00
with rails.	\$950.00	\$950.00	\$950.00	\$950.00	\$950.00	\$950.00
Replace upper						
tier stops and	* - • •	010.00	\$5.00	\$5.00	010.00	¢12.00
cantilever guides	\$5.00	\$12.00	\$5.00	\$5.00	\$12.00	\$12.00
Furnish & install	A 10.00	* 10.00		.	010.00	¢10.00
floor anchors	\$10.00	\$10.00	\$10.00	\$10.00	\$10.00	\$10.00
Furnish & install	** * *		005.00	005.00	005.00	005.00
wall toggle bolts	\$25.00	\$25.00	\$25.00	\$25.00	\$25.00	\$25.00
Furnish & install						
wall anchor	010.00	010.00	010.00	\$10.00	010.00	£10.00
brackets	\$19.00	\$19.00	\$19.00	\$19.00	\$19.00	\$19.00
Furnish & install	69 • • • •			001.00	021 00	021.00
outrigger wheels	\$31.00	\$31.00	\$31.00	\$31.00	\$31.00	\$31.00
Furnish & install						
¹ / ₄ " angle						
cantilever assist						
bracket						,
reinforcement	n/a	\$35.00	n/a	n/a	n/a	n/a
Furnish & install						
skirt board hinge	\$28.00	\$28.00	\$28.00	\$28.00	\$28.00	\$28.00
Supply & install						
replacement						
boards, fir	\$ 8.60 /l.f.	\$ 10.60 /l.f.	\$ 5.50/l.f.	\$ 5.50 /l.f.	\$ 9.60 /l.f.	\$ 9.60 /l.f.
Supply & install						
replacement						
boards, pine	\$ 8.60 /l.f.	\$ 10.60 /l.f.	\$ 5.50 l.f.	\$ 5.50 /l.f.	\$ 9.60 /l.f.	\$ 9.60 /l.f.
Supply & install						
replacement						
boards, plywood						
deck (2' x 8'						
piece)	\$80.00	\$80.00	\$80.00	\$80.00	\$80.00	\$80.00
Install 4" filler	¢ 7 00 /1 £	\$ 7 00 /1 6	\$ 7 00/L 6	\$ 7 00 /LE	\$ 7.00 /l.6	\$ 7 00 /l £
board to fill up gap	\$ 7.00 /l.f.	\$ 7.00 /l.f.	\$ 7.00/l.f.	\$ 7.00 /l.f.	\$ 7.00 /l.f.	\$ 7.00 /l.f.
Furnish & install						
bleacher motion						
alert signal – Edwards Adapta						
Beacon Signal Model 51R-N5-						
40W or approved equal	\$480.00	\$480.00	\$480.00	\$480.00	\$480.00	\$480.00
equal	9480.00	\$480.00	\$480.00	\$480.00	\$480.00	9480.00
	A	В	С	D	E	F

		A STATE OF THE STA			THE	
		INTERKAL			FOLDING	KODIAK
	MEDART/	V.O.S./			R	INDUSTRIES
DESCRIPTION	SAFWAY	HUSSEY	WAYNE	BERLIN	COMPANY	LTD.
Retrofit existing bleachers to						
provide a 16'-0"					-	
section of 48"						
deep						
handicapped						
seating at floor						
level. Price to						
include sides &						
back rails (fixed	\$1 2 00.00	61000.00	61200.00	\$500.00	¢1200.00	\$1200.00
section)	\$1200.00	\$1200.00	\$1200.00	\$500.00	\$1200.00	\$1200.00
Retrofit existing bleachers to						
provide a 16'-0"						
section of 48"						
deep						
handicapped						
seating at floor						
level. Price to						
include sides &						
back rails (one						
retractable section).	\$1200.00	\$1200.00	\$500.00	\$200.00	\$1300.00	\$1300.00
Retrofit existing	\$1200.00	\$1200.00	\$300.00	\$200.00	\$1500.00	\$1500.00
bleachers to						
provide a 16'-0"						
section of 48"						
deep						
handicapped						
seating at floor						
level. Price to include sides &						
back rails (two						
parts, retractable						
section).	\$2100.00	\$2100.00	\$2100.00	\$2100.00	\$2100.00	\$2100.00
Furnish & install						
seat level aisles						
from 36" x 42"						
in width,						
covering the						
distance between the seat board &						
the front riser of						
the row above.	\$90.00	\$95.00	\$15.00	\$15.00	\$78.00	\$78.00
Furnish & install						
deck level aisles.	\$90.00	\$95.00	\$70.00	\$70.00	\$70.00	\$82.00
Add twist						
brackets to						
support end rails	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00
L						

	A	B	С	D	E	F
DESCRIPTION	MEDART/ SAFWAY	INTERKAL/ V.O.S./ HUSSEY	WAYNE	BERLIN	THE FOLDING BLEACHE R COMPANY	KODIAK INDUSTRIE S LTD.
Add delta						
brackets to support end rails	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00
Replace front	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00
row step hinges	\$40.00	\$40.00	\$40.00	\$40.00	\$40.00	\$40.00
Add weights to motor units for even traction	\$45.00	\$45.00	\$45.00	\$45.00	\$45.00	\$45.00
On-site delivery of bleachers (from one school to another school) price per	\$2100.00	62100.00	£2100.00	62100.00	£2100.00	£2100.00
section	\$2100.00	\$2100.00	\$2100.00	\$2100.00	\$2100.00	\$2100.00
Moving and re- anchoring of bleachers within the gymnasium – price per section	\$880.00	\$880.00	\$880.00	\$880.00	\$880.00	\$880.00
Moving and re- anchoring of bleachers within the school –						
price per section Labor cost per hour for repairs	\$1200.00	\$1200.00	\$1200.00	\$1200.00	\$1200.00	\$1200.00
not indicated above or for electrical trouble						
shooting	\$95.00	\$95.00	\$95.00	\$95.00	\$95.00	\$95.00

* Spot sand rough edges, clean spot stain, remove graffiti & apply two (2) coats of water borne polyurethane to bleacher boards.
* Supply specifications and drawings per bid package.
** Supply specifications and drawings per bid package. Price is per motor unit and is to be all inclusive.

BASKETBALL BACKSTOPS

DESCRIPTION	COST
Service one (1) basketball backstop as detailed in Division 13, Section 13125B	
Part 2, Item 2.4 A pages 42 and 43 of specifications	\$110.00
Weld stress crack	\$85.00
Replace pulley	\$98.00
Replace cable (per backstop)	\$170.00
Straighten bent structural steel member (to be approved by Project	
Leader/Structural Engineer)	\$840.00
Replace wall pad	\$65.00
Replace steel pipe (per foot)	\$33.00
Replace pipe fitting	\$75.00
Replace limit switch assembly	\$550.00
Replace key switch	\$185.00
Repair/rebuild existing limit switch	\$510.00
Repair/rebuild existing electric winch	\$1200.00
Replace manual winch (Lyn Russ M/1000)	\$950.00
Replace manual winch (Tork)	\$950.00
Install Lyn Russ A-1000 or DPI WN/-5007 electric winch 115 volt key switch	
operation (power supplied by owner), price to include all conduits	\$1450.00
Install Tork electric winch (power supplied by owner), price to include all	
conduits	\$1425.00
Install cable tension cord with clamps	\$55.00
Install Lyn Russ Auto-Lok safety strap or approved equal (1500# free fall load)	\$460.00
Install Tork safety strap	\$440.00
Install remote receiver on winch	\$250.00
Furnish remote control to receiver	\$210.00
Rewire Key switches	\$95.00
Replace a set of backboard pads	\$265.00
Replace a break-away rim	\$310.00
Labor cost per hour for repairs not indicated above or for electrical trouble	
shooting	\$75.00