

Agenda Item Details

Meeting

Jun 12, 2023 - Regular Meeting

Category

7. Consent Agenda

Subject

7.26 Renewal of Tag-On Bid: ITB 21-968-173 Bleacher Repair & Motorization, presented by Vince Windham,

Program Director, Purchasing, and recommended by the Superintendent for approval.

Access

Public

Type

Action (Consent)

Preferred Date

Jun 12, 2023

Absolute Date

Jun 12, 2023

Fiscal Impact

Yes

Budgeted

Yes

Budget Source

Capital Funds, Project 2310 DW Minor Repair & Maintenance

Recommended

Action

Motion to approve renewing tag-on bid ITB 21-968-173 through Pinellas County Schools, effective through

May 9, 2024.

Public Content

Request approval to renew tagging on to ITB 21-968-173 through Pinellas County Schools. The awarded vendor is Charron Sport Services, Inc.., based on updated awarded bid pricing, the contract will be used as needed. Funds will be paid from Capital Funds, Project 2310 DW Minor Repair & Maintenance. The contract is effective through May 9, 2024, and copies of the renewal documents are attached.

For additional information, please contact Steve Bolton, Program Director, Maintenance & Support Services, at (850) 689-7159.

RENEWAL DOCUMENTS-PINELLAS CO.pdf (158 KB)

Administrative Content

Our adopted rules of Parliamentary Procedure, Robert's Rules, provide for a consent agenda listing several items for approval of the Board by a single motion. Documentation concerning these items have been provided to all Board members and the public in advance to assure an extensive and thorough review. Items may be removed from the consent agenda at the request of any board member.

Motion & Voting

Motion to approve the Consent Agenda and all of the Consent Agenda items as recommended by the Superintendent.

Motion by Tim Bryant, second by Linda Evanchyk.

Final Resolution: Motion Carries

Yes: Tim Bryant, Linda Evanchyk, Diane Kelley, Lamar White



PURCHASING AGENDA ITEM School Board of Pinellas County, Florida

Sch	ool Board Meeting of: May 9, 2023
Bid No: 21-968	8-173 Bleacher Repair & Motorization
Original Bid No:	21-968-173
Recommend approva	l of this agenda item under the specific category checked below.
Agenda Item Catego	ries:
Renewal of Contract	d Request for Proposal Reject Bids Piggy-Back Bid per 6A-1.012 (6) Sale of Property Highest Point Score Re-Award (partial/whole) * State Contract per 6A-1.012 (5) Contract/Bid Termination * Contract Extension * Term: Co-Op Bid pyrighted Materials per 6A1.012 (11)* Direct Negotiation per 6A-1.012 (14) Emergency Ratification *
Contract Period:	5/10/23 thru 5/09/24 N/A - One Time Purchase
Contract Value:	\$ 100,000.00
Contract Type: 🗵	Estimated Firm, Fixed Firm, Fixed Firm, Fixed Dollar Amount Unit Prices Fees or Discounts
Renewal Options:	No. of Terms
* Rationale/Reason	6-months - year
This contract secures repairs.	pricing for gymnasium bleachers and electrical basketball backstops installation and
Reason for Subn	nittal to Board Under Separate Cover:
Bidders Solicited:	Bids Received: Late Bids: Rejected Bids: N/A - Bids Not Required
Submitted By:	Joe Benjamin, NIGP-CPP, CPPO, CPPB For: Countywide
Title:	Director, Purchasing Department
Requested By:	Michael Hewett Buyer: Christine Roney
Title:	Director, Maintenance Department

Recommended award by vendor as follows: (see attached)

BID PROPOSAL FORM

CHARRON SPORTS SERVICES, INC.

UNIT PRICES: BLEACHER REPAIR/REFURBISHMENT/UPGRADE/MOTORIZATION

	Α	В	C	D	E
DESCRIPTION.	MEDART/ SAFWAY	INTERKAL/ V.O.S./HUSSEY	BERLIN	THE FOLDING BLEACHER COMPANY	KODIAK INDUSTRIES LTD.
Perform in-place wood cleaning and refinishing on one (1) typical sixteen (16) ft. section x ten (10) rows high of telescopic bleachers †	\$220.00	\$330.00	\$25.00	\$330.00	\$600.00
Replace missing or broken wheels and axles	\$31.30	\$31.30	\$29.01	\$29.01	\$31.30
Replace missing or non- functioning base springs	\$19.85	n/a	n/a	n/a	n/a
Replace first row locking assemblies	\$94.90	\$90.00	\$94.90	\$90.00	\$90.00
Replace missing or worn brake pads	\$19.85	\$19.85	\$19.85	\$19.85	\$19.85
Replace and/or rebuild first row lock release linkage and first row brake assembly	\$109.00	\$109.00	\$75.00	\$109.00	\$109.00
Replace and/or rebuild damaged row locks/stops	\$.05	\$27.59	\$.05	\$26.00	\$26.00
Straighten bent uprights	\$120.00	\$124.00	\$120.00	\$124.00	\$124.00
Repair/rebuild uprights	\$27.50	\$930.00	\$33.00	\$105.00	\$100.00
Repair/reinforce damaged uprights and bracing	\$65.00	\$95.00	\$33.00	\$95.00	\$95.00

Adjust cantilevers	\$15.00	\$16.00	\$1.00	\$16.00	\$16.00
Replace cantilevers	\$143.00	\$143.00	\$143.00	\$143.00	\$143.00
Weld stress					1
fractures	\$72.00	\$72.00	\$64.74	\$72.00	\$72.00
Repair/rebuild	#1 AA	\$5.39	61.00	05.30	01100
cantilever guides	\$1.00	\$5.39	\$1.00	\$5.39	\$11.00
Repair/rebuild	\$2.16	\$11.00	\$11.00	\$11.00	\$16.50
cantilever stops	\$2.10	\$11.00	\$11.00	\$11.00	\$10.50
Replace each]	
damaged/broken	n/a	\$115.00	n/a	\$115.00	\$124.00
plastic seat module					
Weld seat baffles	\$36.00	\$36.00	\$36.00	\$36.00	\$36.00
Weld seat bracket	\$36.00	\$36.00	\$36.00	\$36.00	\$36.00
Repair cracked	\$11.00	\$11.00	\$31.00	\$31.00	\$31.00
boards					
Replace spring	\$28.00	n/a	n/a	n/a	\$28.00
Replace clip	\$28.00	n/a	n/a	n/a	n/a
Replace lower guide	\$85.00	\$44.00	n/a	\$55.00	\$55.00
(base)	611.00	/-			600.00
Replace nylon guide Replace nylon	\$11.00	n/a	n/a	\$5.00	\$26.00
rollers	\$13.00	\$25.00	n/a	\$30.00	\$26.00
Replace lower stop	\$12.28	n/a	n/a	\$2.00	\$.74
Replace scissors			- 		
linkage	n/a	n/a	\$27.59	n/a	n/a
Replace channel	n/a	n/a	\$16.55	n/a	n/a
Replace bushing/pin	n/a	n/a	\$1.00	n/a	n/a
Supply and install self-storing rails	\$185.00	\$185.00	\$185.00	\$185,00	\$185.00
(aluminum)*	1 05.00	4105.00	\$105.00	\$105,00	W103.00
Supply and install					
self-storing rails	000.00	m141.00	600.00	#14100	0.4.00
(powder-coated	\$99.00	\$141.00	\$80.90	\$141.00	\$141.00
steel)*					
Supply and install					
self-storing mid-	\$235.00	\$235.00	\$235.00	\$235.00	\$224.00
aisle handrails					
Replace motor drive	\$512.00	\$280.00	\$512.00	\$600.00	\$512.00
wheels Supply and install					
motor operation					
system with controls					
(sections tied	\$1,655.00	\$1,725.00	\$220.00	\$1,655.00	\$1,975.00
together as					
banks)**		•			
Replace drive motor	\$620.00	\$1000.00	\$620.00	\$860.00	\$900.00
Replace	n/a	\$990.00	n/a	n/a	n/a
transmission					
Cut off 9" to 10" of	\$1,000.00	\$1,000.00	\$1,000.00	\$1,000.00	\$1,000.00
sections where wall					
interferes with rails.		<u> </u>			
Replace upper tier stops and cantilever	\$5.00	\$13.00	\$5.00	\$13.00	\$13.00
guides					

F	T	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			T
Furnish & install floor anchors	\$11.00	\$11.00	\$11.00	\$11.00	\$11.00
Furnish & install		·			
wall toggle bolts	n/a	n/a	n/a	n/a	n/a
Furnish & install					
wall anchor	\$20.50	\$20.50	\$20.50	\$20.50	\$20.50
brackets		42 0,00	1 020.00	420.50	\$20.50
Furnish & install	624.00	#24.00	024.00	#24.00	201.00
outrigger wheels	\$34.00	\$34.00	\$34.00	\$34.00	\$34.00
Furnish & install					
¼" angle cantilever		\$38.50			
assist bracket	n/a	Ψ30.50	n/a	n/a	n/a
reinforcement					
Furnish & install	\$30.50	\$30.50	\$30.50	\$30.50	\$30.50
skirt board hinge					
Supply & install replacement boards,	\$ 11.69 /l. f.	\$ 11.69 /l. f.	\$ 11.69 /l. f.	\$ 11 60 # C	61160# 6
fir	⊅ 11.07/1. [.	Ф 11.09/L.I.	ф 1 1.09 /1. Г.	\$ 11.69 /l. f.	\$ 11.69 /l. f.
Supply & install					AMILE
replacement boards,					
pine	\$ 11.69 /l. f.	\$ 11.69 /I. f.	\$ 11.69 /l. f.	\$ 11.69 /I. f.	\$ 11.69 /l. f.
Supply & install					
replacement boards,	\$00.00	000.00	600.00	000.00	200.00
plywood deck (2' x	\$88.00	\$88.00	\$88.00	\$88.00	\$88.00
8' piece)					
Install 4" filler board	\$ 7.72 /I. f.	\$ 7.72 /l. f.	\$ 7.72 /l. f.	\$ 7.72 /l. f.	\$ 7.72 /l. f.
to fill up gap			4 /// 2 // 11 11	4 7.7271.1.	ψ /./2/1.1.
Furnish & install bleacher motion			İ		
alert signal –					
Edwards Adapta	\$529.00	\$529.00	\$529.00	\$529.00	\$529.00
Beacon Signal	(\$25.00	ψ329.00	\$525.00	Ψ327.00	Ψ327.00
Model 51R-N5-40W					
or approved equal				,	•
Retrofit existing					
bleachers to					
provide a 16'-0"					
section of 48" deep					
handicapped seating	\$1,324.00	\$1,324.00	\$1,324.00	\$1,324.00	\$1,324.00
at floor level. Price to include sides &					
back rails (fixed			!		
section)					
Retrofit existing	чинани		-	TOTAL TRANSPORTED TO THE PROPERTY OF THE PROPE	
bleachers to provide					
a 16'-0" section of					
48" deep					
handicapped seating	\$1,324.00	\$1,324.00	\$1,324.00	\$1,324.00	\$1,324.00
at floor level. Price				į	!
to include sides &		j			
back rails (one					
retractable section).			- A - A - A - A - A - A - A - A - A - A	***************************************	

Retrofit existing bleachers to provide a 16'-0" section of 48" deep handicapped seating at floor level. Price to include sides & back rails (two parts, retractable section).	\$2,150.00	\$2,150.00	\$2,150.00	\$2,150.00	\$2,150.00
Furnish & install seat level aisles from 36" x 42" in width, covering the distance between the seat board & the front riser of the row above.	\$99.00	\$104.00	\$16.55	\$86.00	\$86.00
Furnish & install deck level aisles.	\$99.00	\$77.00	\$77.00	\$86.00	\$86.00
Add twist brackets to support end rails	\$15.00	\$15.00	\$15.00	\$15.00	\$15.00
Add delta brackets to support end rails	\$14.00	\$14.00	\$14.00	\$14.00	\$14.00
Replace front row step hinges	\$44.00	\$44.00	\$44.00	\$44.00	\$44.00
Add weights to motor units for even traction	\$49.50	\$49.50	* \$49.50	\$49.50	\$49.50
On-site delivery of bleachers (from one school to another school) price per section	\$2,300.00	\$2,300.00	\$2,300.00	\$2,300.00	\$2,300.00
Moving and re- anchoring of bleachers within the gymnasium – price per section	\$950.00	\$950.00	\$950.00	\$950.00	\$950.00
Moving and re- anchoring of bleachers within the school – price per section	\$1,320.00	\$1,320.00	\$1,320.00	\$1,320.00	\$1,320.00
Labor cost per hour for repairs not indicated above or for electrical trouble shooting	\$97.18	\$97.18	\$97.18	\$97.18	\$97.18

[†] Spot sand rough edges, clean spot stain, remove graffiti & apply two (2) coats of water borne polyurethane to bleacher boards.

* Supply specifications and drawings per bid package. Price is per motor unit and is to be all inclusive.

UNIT PRICES: BASKETBALL BACKSTOPS

DESCRIPTION	COST
Service one (1) basketball backstop as detailed in Division 13, Section 13125B Part 2, Item 2.4 A	pages 42 and 43
of specifications	
Weld stress crack	\$129.94
Replace pulley	\$93.00
Replace cable (per backstop)	\$100.00
Straighten bent structural steel member (to be approved by Project Leader/Structural Engineer)	\$175.00
Replace wall pad	\$85,927.00
Replace steel pipe (per foot)	\$36.00
Replace pipe fitting	\$82.50
Replace limit switch assembly	\$575.00
Replace key switch	\$200.00
Repair/rebuild existing limit switch	\$562.00
Repair/rebuild existing electric winch	\$1,324.50
Replace manual winch (Lyn Russ M/1000)	\$.048
Replace manual winch (Tork)	\$.048
Install Lyn Russ A-1000 or DPI WN/-5007 electric winch 115volt key switch operation (power supplied by owner), price to include all conduits	\$1,610.00
Install Tork electric winch (power supplied by owner), price to include all conduits	\$1,615.00
Install cable tension cord with clamps	\$60.00
Install Lyn Russ Auto-Lok safety strap or approved equal (1500# free fall load)	\$505.00
Install Tork safety strap	\$516.00
Install remote receiver on winch	\$448.00
Furnish remote control to receiver	\$231.00
Rewire Key switches	\$100.00
Replace a set of backboard pads	\$290.00
Replace a break-away rim	\$340.00
Labor cost per hour for repairs not indicated above or for electrical trouble shooting	\$76.72